

REPLACEMENT TILT/ TRIM MOTORS & REPAIR KITS



The Leader in Marine Electrical Parts.



DO NOT CUT WIRES OR DISMANTLE UNITS

Cutting a unit's wires or dismantling a unit immediately voids the manufacturer's warranty. Water can easily seep into the motor through cut wiring. In addition, taking a motor off the reservoir and trying to install it on an old reservoir usually damages the brushes in the motor. Disassembled parts are not covered by warranty.

6204 (NEW)
FITS: O.M.C.
3-wire connection
2-bolt mount

TR204
Repair kit



6206 (NEW)
FITS: O.M.C.
3-wire connection
3-bolt mount

TR206
Repair kit



6208 (NEW)
(MOTOR/RESERVOIR ONLY)
FITS: O.M.C.
3-wire connection

TR208
Repair kit



6209 (NEW)
FITS: O.M.C.
2-wire connection

TR209
Repair kit



6211 (NEW)
FITS: O.M.C.
stern-drive 1979-1985
2.5L, 3.0L
3-wire connection

TR211
Repair kit
(Cast Aluminum)

TR210
Repair kit
(Stamped Steel)



6213 (NEW)
FITS: GOOD AUTOMATIC WINDLASS
 Ring Terminal Ends



Will also replace units with this style shaft



6217 (NEW)
(MOTOR/RESERVOIR ONLY)
FITS: B.M.W., MERCURISER VOLVO PENTA
 Includes: Screws, gasket & adapter
 Ring Terminal Ends



TR217
 Repair kit



TAK217
 Screws, gasket, adapter



6214 (NEW)
MOTOR/RESERVOIR ONLY
FITS: O.M.C.
1979-1985 3.8L, 4.3L, 5.0L, 5.7L
 Stern Drive Engines
 2-wire connection



6218 (NEW)
(MOTOR ONLY)
FITS: MERCURISER I/O'S AND MERCURY OUTBOARDS W/OILDYNE PUMP
 12 Volt
 Ring Terminal Ends



TR218
 Brush kit



Replaces early square-style motor



6216 (NEW)
(MOTOR/RESERVOIR ONLY)
FITS: CHRYSLER, O.M.C.
 3-wire connection



6219
 Slow speed motor
 Fits Jack lift for racing outboards

REPLACEMENT TILT/ TRIM MOTORS & REPAIR KITS



The Leader in Marine Electrical Parts.



6220 (NEW)
HEAVY-DUTY
FITS: O.M.C.
2-wire connection
Includes O-ring
3-bolt mount
Male Spade Terminal Ends
96" Leads



R473
Relay available

6220X (NEW)
HEAVY-DUTY, FITS: O.M.C.
2-wire connection, Includes O-ring, 3-bolt mount
Male Spade Terminal Ends
62" Leads



6223 (NEW)
HEAVY-DUTY
FITS: VOLVO PENTA
Female Spade Terminal Ends



6224 (NEW)
(COMPLETE)
FITS: VOLVO PENTA
Includes: Hydraulic valve body
Ring Terminal Ends



6225 (NEW)
(MOTOR/ RESERVOIR ONLY)
Fits: PRESTOLITE

To be discontinued
when present stock
is exhausted



← Replaces this style
Prestolite Pump

6227 (NEW)
(COMPLETE)
FITS: VOLVO PENTA - THRU 1999
W/OILDYNE PUMP



6232
(MOTOR ONLY)

M531 (NEW)
RESERVOIR KIT
FITS: ARCO 6227
Includes: Reservoir,
cap, and O-ring



Fits Oildyne Pump ONLY

For new style 4 screw
mount see M533 in
miscellaneous section

6228 (NEW)
HEAVY-DUTY
(MOTOR ONLY)
FITS: MANY SMALL
O.M.C. OUTBOARDS
Includes gasket



Fits: O.M.C. Pump
No. 173946

TR228
Repair kit



6231 (NEW)
(MOTOR ONLY)
FITS: U.S. MARINE
W/OILDYNE PUMP
 2-wire connection
 Female Spade Terminal Ends



6239 (NEW)
HEAVY-DUTY
FITS: HONDA
1992-Up 35-50 HP
 2-wire connection
Includes O-ring
4-bolt mount
Hollow-hex shaft
 Female Spade Terminal Ends



6232 (NEW)
(MOTOR ONLY)
FITS: ARCO 6227,
LATE MODEL
VOLVO PENTA
W/ OILDYNE PUMP
 2-wire connection



NOTE:
 Distance between mounting bolts: 2.5"
 Bolt size: 10x32 coarse thread

6240 (NEW)
HEAVY-DUTY
FITS: YAMAHA
1997-UP 115 HP
2000-UP 115 HP 4-Stroke
1997-2000 130 HP
1997-UP 150-200 HP
1998-UP 225 HP
 2-wire connection
4-bolt mount,
 Ring Terminal Ends
Includes O-ring



6233 (NEW)
Fits: LATE MODEL
VOLVO PENTA SX
MODELS.
 Replaces Teleflex Motor and Volvo part number 3861575



NOTE:
 Distance between mounting bolts: 2.3"
 Bolt size: 10x24 coarse thread

6241 (NEW)
HEAVY-DUTY
FITS: O.M.C. 60, 70, 90,
115, 150, 175 HP
1991-Up 200, 225 HP
1991-94 120, 140 HP
1995-UP 50 HP 3-cyl, 60 HP,
V4 130 HP
1997-Up 115-200 HP
1998-99 225 HP
 2-wire connection
4-bolt mount
Flat-blade shaft
 Female Spade Terminal Ends



Includes O-ring and adaptor to replace motors with hollow hex shafts

ALSO REPLACES OEM MOTORS WITH HOLLOW HEX SHAFT

R473
 Relay available



REPLACEMENT TILT/ TRIM MOTORS & REPAIR KITS



The Leader in Marine Electrical Parts.



6242 (NEW)

HEAVY-DUTY

FITS: O.M.C.

1992-Up J-suffix 40,
48, 50 HP

2-wire connection

Includes O-ring

4-bolt mount

Hollow-hex shaft

Female Spade Terminal Ends



R473

Relay available

6243 (NEW)

HEAVY-DUTY

FITS: O.M.C.

1989-1992 M-suffix 40,
48, 50 HP

2-wire connection;

4-bolt mount

Includes O-ring

Hollow-hex shaft

Male Spade Terminal Ends



R473

Relay available

6244 (NEW)

HEAVY-DUTY

FITS: O.M.C.

1993 V6

1993-Up Commercial V8

2-wire connection;

3-bolt mount

Includes O-ring

Flat-blade shaft

Female Spade Terminal Ends



R473

Relay available

6245 (NEW)

HEAVY-DUTY

FITS: O.M.C. COBRA

1989-1993 Stern drives
(all models)

VOLVO 1994-UP 3.0-8.2L

2-wire connection;

3 bolt mount

Includes O-ring

Flag Connector Terminal Ends



To be discontinued when
present stock is exhausted

6247 (NEW)

HEAVY-DUTY

FITS: EVINRUDE ETEC

2005-2009 70-90 HP

2007-2009 115 HP

2009- 130 HP

Includes O-ring



TAK247

Mounting bolts, flat washers,
O-ring and couplers for
tilt/trim motors

Available late April 2012

6248 (NEW)

HEAVY-DUTY

FITS: EVINRUDE ETEC

2005-2009 40-50 HP

2006-2009 60 HP

2009- 25-30 HP

Includes O-ring



Available late April 2012

6250 (NEW)

HEAVY-DUTY

FITS: Late model MERCURY

135, 150 XR6, Magnum III,

175, 200, 225, 250 HP,

105-140 HP Jet

2-wire connection; **2-bolt mount**

Includes O-ring Flat-blade shaft

Bullet Connector Terminal Ends



This motor will NOT replace an early
model Mercury cartridge pump motor!
Order Part No. 6278

6255 (NEW)
HEAVY-DUTY
FITS: Late model
MERCURY/FORCE
25-50 HP outboards
2-wire connection
4-bolt mount
Flat-blade shaft
Bullet Connector
Terminal Ends



6261 (NEW)
HEAVY-DUTY
FITS: YAMAHA
2003-Up 75, 80, 90 &
100 HP Outboard Engines
Includes O-ring



6259 (NEW)
HEAVY-DUTY
FITS: YAMAHA
2001-2004 50 HP 4 Stroke
2002-2004 60 HP 4 Stroke
2001-2006 40 HP 2 Stroke (TLR)
2003-2009 50 HP 2 Stroke (TLR)
Includes O-ring



6263 (NEW)
HEAVY-DUTY
FITS: YAMAHA
2002-2009 200, 225,
250 HP 4 Stroke
2002-2009 200-300 HP
2 Stroke
Includes O-ring



Available late May 2012

6264 (NEW)
HEAVY-DUTY
FITS: YAMAHA
1985-1992
40-50 HP **4 bolt mount,**
2-wire connection
Includes O-ring



6260 (NEW)
HEAVY-DUTY
FITS: YAMAHA
1992-2002 90 HP
1992-1995 50-90 HP
1994 40 HP; 1996 70-90 HP
1997-Up 60, 70, 90 HP
2-wire connection,
3-bolt mount
Includes O-ring
Flat-blade shaft
Ring Terminal Ends



6265 (NEW)
HEAVY-DUTY
FITS: YAMAHA
1987-1995
115-200 HP Outboards
1990-1993 225 HP
2-wire connection
3-bolt mount
Includes O-ring
Flat-blade shaft
Ring Terminal
Ends



REPLACEMENT TILT/ TRIM MOTORS & REPAIR KITS



The Leader in Marine Electrical Parts.



6266 (NEW)
FITS: YAMAHA
1995-Up 40/50 HP
2-wire connection
3-bolt mount
Includes O-ring
Ring Terminal Ends



6270 (NEW)
(COMPLETE)
FITS: Late model MERCURY
225-275 HP Outboards w/Oildyne pump
Ring Terminal Ends



6271 (NEW)
(COMPLETE)
Slow speed unit used for racing
applications

6267 (NEW)
FITS: YAMAHA
Early 70, 90,115,
150-200 HP
3-wire connection
3-bolt mount
Ring Terminal Ends
4-mm thick shaft
blade with 68.3-mm
mounting collar.
Includes O-ring



6274 (NEW)
HEAVY-DUTY
FITS: Late model
MERCURY/MARINER
& FORCE 75-125 HP
outboards w/single
ram 3-wire connection;
4-bolt mount
Hollow-hex shaft
(Motor/Reservoir Only for Trim
Pump Assembly 824051)
Includes stainless steel
mounting screws,
shaft adaptor, O-ring
and fill plug.
Ring Terminal Ends



6268 (NEW)
FITS: SUZUKI
1991-1997 DT90,
1991-2000 DT100,
1991-2003 DT150,
1991-1992 DT175,
1991-2000 DT200,
1991-2003 DT225
2-wire connection
3-bolt mount
Includes O-ring and adaptor
Ring Terminal Ends



6275 (NEW)
(COMPLETE)
FITS: Late model MERCUISER
w/Oildyne pump
Ring Terminal Ends



6218 MOTOR ONLY

M525 (NEW)
Reservoir kit
FITS: ARCO 6275
Includes: Reservoir, cap, O-ring,
mounting screw



For new style 4 screw mount
Mercuriser 883166A2 see M532
in miscellaneous section




6276 (NEW)
HEAVY-DUTY
FITS: Late model
MERCURY/MARINER, FORCE
 40-125 HP outboards
 w/single ram
 2-wire connection
4-bolt mount

Hollow-hex shaft
 (Motor/Reservoir Only)
**Includes stainless
 steel mounting screws, shaft adaptor,
 O-ring and fill plug.**
 Bullet Connector Terminal Ends



Will also replace these style units →



TAK276
 Mounting bolts, O-ring, fill cap and
 shaft adapters for tilt/trim motors



6277 (NEW)
HEAVY-DUTY
(MOTOR ONLY)
FITS: **cartridge pump 6278 only!**
2-bolt mount
 Ring Terminal Ends



TR277
 Repair kit



Motor WILL NOT replace original equipment. Order Part No. 6278


6278 (NEW)
(COMPLETE)
HIGH-PERFORMANCE
 Cartridge pump
 w/replaceable motor
Fits: MERCURY/MARINER
 35-220 HP Outboards
2-bolt mount

w/Design I, 3 ram,
 3-wire tilt/trim units
W/SIDE FILL RESERVOIR
 Replaces square-style Eaton,
 round-style Prestolite



TR277
 Repair kit

SIDE FILL RESERVOIR



6279 (NEW)
HEAVY-DUTY
FITS: MERCURY/MARINER
 outboards w/Design II
 3 ram, three-wire trim units
 Hollow-hex shaft
W/AFT FILL RESERVOIR
 3-wire connection
2-bolt mount
Shaft adaptor and
O-ring included.
 Ring Terminal Ends



← Replaces this square motor

TR279
 Repair kit

AFT FILL RESERVOIR

